



Description:

Here's the quick, easy and effective way to remove a wide range of coatings from a variety of surfaces. LIFT-OFF's special gel formula stays where it's sprayed, enabling the stripping agents to completely penetrate and lift coatings with ease. Lifts most paints and gaskets in 10-20 minutes. Use LIFT-OFF™ on metal, glass, fiberglass, urethane auto parts, wood, flexible parts and rigid parts. •Not recommended for use on plastic tile, linoleum or synthetic fabrics.

LIFT-OFF™ Paint and Gasket Stripper

Directions:

IMPORTANT: Read directions and cautionary statement below before proceeding. Wear eye protection, cover exposed body surfaces with gloves, long sleeves and pants. Use in well ventilated area.

1. Shake can for 1 minute.
2. Mask off areas not to be stripped.
3. For urethane bumpers and other urethane parts, clean surface first with Well•Worth's TASK MASTER™ Cleaning Solvent or similar product.
4. Hold can 8-10 inches from surface and spray. Apply a heavy coating.
5. Allow product to work for 10-15 minutes. Depending on the type of coating and surface being worked on, use putty knife, squeegee, rags or steel wool.

NOTE: A second application may be necessary to remove stubborn adhesive. On urethane bumpers and pans, flush with water and clean with TASK MASTER™ solvent. Use caution on all flexible and fiberglass parts. **DO NOT** leave LIFT-OFF™ on for more than 25 minutes. When paint loosens, remove at once. If slight swelling occurs, rinse thoroughly and part will return to original shape after 2-4 hours.

Uses:

REMOVES:

- Base and Clear Coats
- Enamels
- Primers
- Epoxies
- Tar
- Lacquers
- Acrylics
- Varnishes
- Shellac
- Gaskets
- Decals
- Carbon

Packaging:

#3002 - 20 oz. Aerosol Can.....12 per case

For complete product specifications, review the product SDS at wellworthproducts.com.

Storage:

Keep away from heat, sparks or open flame. Store at temperatures below 120°F (50°C). Do not puncture, incinerate or burn can.

First Aid Measures:

- **EYE CONTACT:** Wash eyes with fresh water. If irritation continues, get medical attention.
- **SKIN CONTACT:** Wash skin with soap and fresh water. If irritation continues, get medical attention.
- **INHALATION:** Remove to fresh air. Give oxygen. Get medical attention.
- **INGESTION:** Do not induce vomiting-gastric lavage. Get medical attention.

ChemTrec (USA) 800-424-9300

HMIS HAZARD RATING

0-Least	A-Goggles	Health..... 3
1-Slight	B-Goggles, Gloves	Flammability..... 3
2-Moderate	C-Goggles, Gloves	Reactivity..... 0
3-High	Protective Wear	Personal Protection..... B
4-Extreme		

NOTICE TO PURCHASER: Well•Worth Products, Inc. provides no warranty of any kind with respect to the product, whether express or implied including without limitation, the implied warranty of merchantability or fitness for any intended use or purpose; shall not be liable under any circumstances for any loss, damage, liability, injury or expense directly or indirectly resulting from, arising or related to the use or application of product; shall not be liable for consequential or incidental damages or loss of profits; and its liability shall be limited to replacement of the product. **ALWAYS CONSULT MSDS for further details on precautions for safe handling and use.**