



POWER BLAST™



POWER BLAST'S cutting-edge formula is biodegradable and phosphate free all purpose cleaner. Cleans better and rinses easily to remove a variety of soils, greases and stains. Concentrated formula can be diluted as needed. Leaves a fresh lemon scent and an invisible coating that helps keeps surfaces cleaner longer. POWER BLAST™ is a safe non-flammable formula that can be used on hard surfaces as well as rugs, upholstery, and cloth surfaces.

Directions:

DIRECTIONS:

Note: Safety glasses and rubber gloves are recommended. To prevent spotting or damage, do not apply full strength without testing a small hidden area. Do not allow POWER BLAST™ to dry on surface.

FOR HARD SURFACES:

1. Dilute up to 1:16 with water.
2. Spray directly on surface to be cleaned.
3. Allow product to work 2-5 minutes.
4. Rinse thoroughly with water.

FOR RUGS, UPHOLSTERY, CLOTH SURFACES:

1. Mix one quart concentrate into 5 gallon pail.
2. Spray a strong stream of water into pail to create a mound of suds.
3. Apply suds to surface to be cleaned with brush or sponge. For best results brush in a circular motion to clean.
4. Wipe dry with a clean cloth.

Product Number and Packaging:

#21161 - 1 Gallon

#21165C - 5 gallon Cube

#211655 - 55 Gallon Drum

For complete product specifications, review the product SDS at wellworthproducts.com.

Storage:

Do not allow product to freeze. Keep away from children.

First Aid Measures:

EYE CONTACT: Rinse thoroughly with plenty of water for at least 15 minutes.

DO NOT rub eyes. If irritation persists, seek medical attention.

SKIN CONTACT: Wash off immediately with plenty of soap and water. If skin irritation persists, call a physician.

INHALATION: Move to fresh air immediately.

INGESTION: Do NOT induce vomiting. Seek medical attention immediately. If person is conscious, give two glasses of water to dilute the ingested material. Follow up with several glasses of fruit juice or very diluted vinegar or carbonated soda to neutralize the material.

STORAGE: Keep away from children. Store in a cool dry place. Do not store below 32 degrees F. Do not store in direct sunlight.

Chemtrec (USA) 800-424-9300

800-890-7935

www.wellworthproducts.com