



180 Dutton Avenue
 Buffalo, NY 14211
 www.wellworthproducts.com
 1-800-890-7935
 Date Prepared: 2/15/08

EXCEL™ Heavy Duty Anti-Seize Lubricant

DESCRIPTION

Excel™ is a copper rich formula that provides superior lubrication and protection under the most adverse and corrosive conditions. Assures accurate torquing and easier assembly and disassembly of parts. Superior formulation is not effected by acids, solvents, oils, alkalis, gasoline, salt water, and other chemicals. Maintains a higher degree of electrical conductivity. For use on plastics, fiberglass and all metals (including all alloys of steel, aluminum, brass and copper).

USES

- Manifold Studs • Cylinder Head Bolts • Bushings • Couplings • Spark Plug and Oxygen Sensor Threads • EGR Fittings • Splines • Drive Chains • Electrical Conduit Connections • Gears • Sprockets • Lever Pivots • Roller and Hinge • Brake Lube Assembly • Engine Head Bolts • Starter and Alternator Bolts • Much More

DIRECTIONS

FOR BEST RESULTS ALL SURFACES MUST BE CLEAN AND FREE OF GREASE. AEROSOL DIRECTIONS: 1. SHAKE CAN WELL BEFORE USE. 2. Spray Excel™ to completely cover part. 3. Assemble part. 4. Follow manufacturer's specs when accurate torquing is required. 5. When job is completed, clean valve by inverting the can and spraying until only pressure escapes.

BRUSH TOP DIRECTIONS: 1. Apply a light coating of compound to parts. 2. Assemble parts. 3. Wipe away excess compound.

PACKAGING

- # 3006 - 12 oz. Aerosol Can
- # 5016 - 8 oz. Brush Top Can
- 12 Per Case

STORAGE

Do not store in temperatures above 120°F (50°C). Do not puncture, incinerate or burn. Keep away from heat, sparks or open flame.

SPECIFICATIONS

- FLASH POINT : Propellant/Product; -156° F
- EVAPORATION RATE (Butyl Acetate = 1) : Faster Than
- COLOR : Copper Color
- ODOR : Solvent Odor
- SOLUBILITY IN WATER : Negligible

HMIS HAZARD RATING

0-Least	A-Goggles	HEALTH	2
1-Slight	B-Goggles, Gloves	FLAMMABILITY	4
2-Moderate	C-Goggles, Gloves, Protective Wear	REACTIVITY	0
3-High		PERSONAL PROTECTION	A
4-Extreme			

FIRST AID MEASURES

EYE CONTACT: Immediately flush eyes with plenty of water. Remove clothing. Get medical attention, if irritation persists. SKIN CONTACT: Immediately flush skin with plenty of water. Remove clothing. Wash clothing separately before reuse. Get medical attention immediately. INHALATION: Remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Contact physician immediately. INGESTION: Get medical attention immediately. If swallowed, do NOT induce vomiting. Give victim a glass of water or milk. Call a physician or poison control center immediately. Never give anything by mouth to an unconscious person. ChemTrec (USA) 800-424 9300.

NOTICE TO PURCHASER: Well•Worth Products, Inc. provides no warranty of any kind with respect to the product, whether express or implied including without limitation, the implied warranty of merchantability or fitness for any intended use or purpose; shall not be liable under any circumstances for any loss, damage, liability, injury or expense directly or indirectly resulting from, arising or related to the use or application of product; shall not be liable for consequential or incidental damages or loss of profits; and its liability shall be limited to replacement of the product.

ALWAYS CONSULT MSDS for further details on precautions for safe handling and use.