



PRISMA™

ACRYLIC ENAMEL PAINTS



Professional formula provides superior coverage in a durable finish that won't crack, chip or peel. Use on metal, wood, fiberglass, automotive engines or anywhere a quality coating is desired. PRISMA™ paints are lead-free and have no ozone-depleting chemicals. Fast dry formula enables you to touch painted surfaces in a little as 15-20 minutes.

Directions:

1. IMPORTANT: NEVER SPRAY ON HOT PARTS (ENGINES, ETC.)
2. Surface to be painted must be clean and dry. Remove all grease, grime, oil, etc., using a solvent such as Well Worth's TASKMATER™. Remove all rust.
3. SHAKE WELL. Mixing ball must move freely for one minute. Repeat this periodically.
4. Use at room temperature (approximately 70°F). Mask off areas not to be painted.
5. Holding can about 10-12 inches from surface, spray in smooth even strokes. Use a side-to-side motion and release spray head after each stroke. Overlap adjacent painted areas for a continuous finish.
6. Two thin coats are better than one heavy coat. Apply second coat immediately.
7. Clean valve by turning can upside down and spraying until only pressure escapes.

Product Number and Packaging:

#4002 - Net wt. 12 oz. Aer.....12 per case

For complete product specifications, review the product SDS at wellworthproducts.com.

Storage:

Do not store in temperatures above 120°F (50°C). Do not puncture, incinerate or burn. Do not place near sources of heat. Keep from freezing.

First Aid Measures:

- EYE CONTACT: Rinse open eye for several minutes under running water. If symptoms persist, get medical attention.
- SKIN CONTACT: Remove contaminated clothing. Wash exposed area with soap and water.
- INHALATION: If breathing is difficult, administer oxygen. Get medical attention.
- INGESTION: Get medical attention immediately.

ChemTrec (USA) 800-424-9300

800-890-7935

www.wellworthproducts.com