



# PRISMA™

## ACRYLIC ENAMEL PAINTS



Professional formula provides superior coverage in a durable finish that won't crack, chip or peel. Use on metal, wood, fiberglass, automotive engines or anywhere a quality coating is desired. PRISMA™ paints are lead-free and have no ozone-depleting chemicals. Fast dry formula enables you to touch painted surfaces in a little as 15-20 minutes.

### Directions:

1. IMPORTANT: NEVER SPRAY ON HOT PARTS (ENGINES, ETC.)
2. Surface to be painted must be clean and dry. Remove all grease, grime, oil, etc., using a solvent such as Well Worth's TASKMATER™. Remove all rust.
3. SHAKE WELL. Mixing ball must move freely for one minute. Repeat this periodically.
4. Use at room temperature (approximately 70°F). Mask off areas not to be painted.
5. Holding can about 10-12 inches from surface, spray in smooth even strokes. Use a side-to-side motion and release spray head after each stroke. Overlap adjacent painted areas for a continuous finish.
6. Two thin coats are better than one heavy coat. Apply second coat immediately.
7. Clean valve by turning can upside down and spraying until only pressure escapes.

### Product Number and Packaging:

#4003 - Net wt. 12 oz. Aer.....12 per case

For complete product specifications, review the product SDS at [wellworthproducts.com](http://wellworthproducts.com).

### Storage:

Do not store in temperatures above 120°F (50°C). Do not puncture, incinerate or burn. Do not place near sources of heat. Keep from freezing.

### First Aid Measures:

- EYE CONTACT: Rinse open eye for several minutes under running water. If symptoms persist, get medical attention.
- SKIN CONTACT: Remove contaminated clothing. Wash exposed area with soap and water.
- INHALATION: If breathing is difficult, administer oxygen. Get medical attention.
- INGESTION: Get medical attention immediately.

ChemTrec (USA) 800-424-9300

800-890-7935

[www.wellworthproducts.com](http://www.wellworthproducts.com)