

LASER™ PENETRATING OIL



PROTECTS AND LUBRICATES. PIN POINT SPRAY PENETRATES RUSTED PARTS FAST.

DER PRESSURE: VAPOR HARMFUL HARM OR FÄTAL IF SWALLOWED: EVE SKIN AND RESPIRATORYTRACTIRRITANT. KEEP OUT OF REACH OF CHILDREN-Read other cartions on back pamel. NET WT. 11.5 oz. (3269) LASER's[™] pin-point spray sends a proprietary blend of penetrating oils and lubricants that attack corrosion and loosen rusted parts and lubricate mechanisms. LASER[™] is also an effective aid for moisture displacement on motors and equipment. LASER[™] leaves behind a protective shield that helps prevent future rust and corrosion.

800-890-7935

Directions:

SHAKE CAN WELL BEFORE AND DURING USE. Spray LASER[™] on rusted or corroded parts. Allow 2-3 minutes for LASER[™] to penetrate. Tapping parts will help accelerate the penetrating action. On extremely corroded parts a second application may be needed.

TO DISPLACE MOISTURE: Make sure all electrical connections are off, disconnected and parts are cool to the touch before spraying engine or equipment. Allow adequate time for spray to dry completely before reconnecting any electrical components.

Product Number and Packaging: #5011 - 12 per case

CONTAINS: Hydrocarbon Solvent, Isopropyl Alcohol, Xylene, 2-Butoxyethanol, Carbon Dioxide, Nonylphenoxypolyethoxyethanol, Mineral Oil Dewaxed, Tolune, Ethylene Glycol, Ethyl Benzene, Ethylene Oxide.

For more information, refer to the Well Worth Safety Data Sheet for this product, or call ChemTrec (USA) 800-424-9300.



www.wellworthproducts.com

DANGER: Causes skin irritation. Causes serious eye irritation. May be fatal if swallowed and enters airways. Extremely Flammable Aerosol. Contains gas under pressure; may explode if heated.

Precautionary Statements/Prevention: Wash face, hands and any exposed skin thoroughly after handling. Wear protective gloves, eye protection, face protection. Avoid breathing fumes, gas, mist, vapors, spray. Use only outdoors or in a well-ventilated area. Keep away from heat, sparks, open flames, hot surfaces- no smoking. Do not spray on open flame, or other ignition source. Pressurized container: Do not pierce or burn, even after use. Do not expose to temperatures exceeding 50°C /122°F. Store in a well-ventilated place. Keep container tightly closed. Protect from sunlight. Store locked up. Dispose of contents/container to an approved waste disposal plant.

FIRST AID: IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor/physician if you feel unwell.

IF ON SKIN: Wash with plenty of soap and water. If skin irritation persists, get medical advice/attention. Take off contaminated clothing and wash it before reuse.

IF SWALLOWED: Immediately call a POISON CENTER or doctor/physician. Do NOT induce vomiting.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice/attention.